




068010.2	POTENZIOMETRO 10 kOhm CON INT. ON.OFF SENZA FILI POTENTIOMETER 10 kOhm WITH INT. ON.OFF WIRELESS
----------	---

DESIGNATED CHARACTERISTICS					QC1	KPC		
0		LAST NO USED		K OR Q IN SYMBOL INDICATES CHECKPOINT	FIT/FUNCTION	 CI	 FF	
1	0	TOTAL ON DRAWING						
KPC	QC1					SAFETY/COMPLIANCE		 SC
NO	NO	TYPE	DESCRIPTION	RATIONALE		ZONE	SH	PTS
1		FF	TUTTA LA LUNGHEZZA			C7		

